

MP900 Quick Reference Guide

(QRG)

Contents

MP920 Memory Map

MP920 Register Addressing

General Startup Procedure

MPE720 Serial and Ethernet Connection

Module Configuration Procedure for Demo

Basic Register Set

Motion Command Code: Indexing

Function Block Startup Procedure

Motion Program Startup Procedure

Motion Program Work Registers

Data Trace

Reference Units

MP920 Memory Map

Register Memory	S (Global) SW0000-1023 System information and status (read only) <i>Example: Flicker relays, Calendar, Scan time setting, error codes, ect.</i>	C (Global) CW00000-04095 Constant, Read only registers. <i>Data that end user can change without needing to access the program.</i>	M (Global) MW00000-32767 General Multi-Purpose read/write registers *Function Block RDA: MW00000-03999 <i>Axis#1: MW100-199, Axis#2: MW200-299...</i>	D E C I M A L
	Fixed Parameters (for each axis) Written to in Module Configuration	<i>Example:</i> Mechanical system specifications (pulley ratios, encoder counts per load rev)	User Free: MW04000-32767 Convention: <i>Axis#1: MW1000-1999, Axis#2: MW2000-2999</i> Reference: RDA Spreadsheet * If using motion function blocks.	
	Define axis units, motor specs. Cannot be written by ladder Changes usually require power cycle	Reference:		
	I (Input) IW0000-FFFF "Motion Monitoring" general purpose & motion data (Read only by application program)	O (Output) OW0000-FFFF "Motion Setting" general purpose & motion data (Read/Write by application program)	Physical Outputs: OW0000-7FFF Convention: OW0000-0100 for Local IO modules OW0100+ for SVB and M-LINK I/O	
Physical Inputs: IW0000-7FFF Convention: IW0000-0100 for Local IO modules IW0100+ for M-LINK Network I/O	Axis (Motion) Input: IWC000-FFFF (for axis #1) "motion monitoring" Offset 40h per axis 400h per module/circuit <i>Example: IBC000 Q = axis#1 controller ready</i> Reference: Motion Module User Man 6.2.2	Axis (Motion) Output: OWC000-FFFF (for axis #1) "motion setting" Offset 40h per axis 400h per module/circuit <i>Example: OBC000 Q = turn axis#1 servo on</i> Reference: Motion Module User Man 6.2.3	H E X A D E C I M A L	
D (Local Registers)* DW00000-16383 Used as general purpose read/write in the defined Drawing only.	Suggested Bits: DW00000-00008 (DB000000~DB00008F) Convention: One-Shot DW00009 (DB000090~DB00009F) Word Operations: DW00010-00025 (These can be 16-bit integers, 32-bit integers, or 32-bit Accumulators: DW00026 (16-bit Integer accumulator) DW00027 (16-bit Logic [Hexadecimal] Accumulator) DL00028 (32-bit Long Accumulator) DF00030 (32-bit Floating point Accumulator) Long DW00032-00089 } Float DW00100-00256 } If local registers are increased as mentioned below.			D E C I M A L
*Default is 32 D-registers per drawing. R-click drawing in File Manager - increase to 256 when using Function Blocks. Reference:				
# ("Sharps") #W00000-16383 Local Constants. General purpose, read-only by the specified Drawing they are defined in.	Module Configuration Each hardware module on the rack has several configuration files. This data is stored in program memory.			
Set up via a table in the "properties" dialog box for each drawing. Rarely Used		New project requires setting Module Configuration first. Select from File Manager under Definition Folder"		
Drawings: H, L, A, I	H (High Scan) Use for all code that runs motion related functions. 2ms is usually good. L (Low Scan) Use for code that runs HMI, or user operated switches, lights, etc. 20ms is usually good A (Startup) Use for drawings that should automatically run once at controller power up. S (System) MP940 only - rarely used. Scan as fast as 250us for short drawings. I (Interrupt) Use to run a special interrupt routine after receiving a local input defined as a dedicated "Interrupt."			


MP900 Register Addressing

DRAWINGS

All registers except Input and Output : S, C, M, D, #, A

Address

MW2008
 MW2009
 MW2010
 MW2011



M B 2008 C i


Register Type S: System C: Global Constant M: Multi-Purpose User D: User Local #: Local Constant A: Startup	Data Type B: Bit W: 16-bit Word L: 32-bit Long F: 32-bit Float A: Address	Register Number (Decimal)	Bit Number (Hex) <i>If Bit Data Type</i>	Subscript (optional) i or j
--	---	----------------------------------	--	---------------------------------------

DRAWINGS

Input and Output Registers

Address

OW8018
 OW8019
 OW801A
 OW801B



O B 8019 A

Register Type O: Output (Motion Setting) I: Input (Motion Monitoring)	Data Type B: Bit W: 16-bit Word L: 32-bit Long F: 32-bit Float	Register Number (Hex)	Bit Number (Hex) <i>If Bit Data Type</i>
--	---	------------------------------	--

MP900 Startup Procedure

All equipment must be properly wired and installed.
 Rotary switch for M-LINK node number must be set on all axes and I/O nodes
 Communication Manager must be configured for serial communication

Step	Instruction	Detail
1	Power OFF	Prepare for first Power ON
2	Set only TEST and INIT dipswitches ON	Prepare to erase all RAM (not FLASH)
3	Power ON	Wait for RDY and RUN to flash. <i>Takes about 3sec.</i>
4	Set only RUN dipswitch ON & Cycle power	The controller is initialized to factory settings
5	Start MotionWorks MPE720	Connect Serial Cable JEPMC-W5311-03B
6	Create new Group folder, Order subfolder, and Controller subfolder	R-click to create. Type any name 8 characters or less, no spaces. Choose "Controller Type" as MP920
7	R-Click CPU folder and select "Online"	Changes will be made to files on the computer as well as on the controller, instead of just the computer.
8	Double-click CPU folder to Log On	The default User Name and Password are both USER-A
10*	Click the Black Diskette Icon (FLASH Save)	When the window pops up, click the leftmost button (Save/Compare) and accept other defaults. Close window when complete.

* Step 10 is optional as all settings are saved by battery backup.

SERVOPACK Default Set Procedure

(Optional Procedure) When servopack is not brand new, use this procedure to restore default parameter settings

Step	Instruction	Detail
1	Log On ONLINE	R-Click CPU folder, Log OFF. R-Click CPU folder, check "online". Double-click Controller folder to log on. The default User Name and Password are both USER-A
2	Open Servopack Module Configuration	From file manager, under Definition folder, open Module Configuration. Engineering Manager application opens. Double-click SVB slot number (or R-click - Open Slot). In the SVB Definition window, Select SERVOPACK tab
3	Save defaults for each axis	Choose the Axis number from the pull-down list (top left) Under Edit menu, choose Default Set, click OK and Save Repeat for each axis as necessary Cycle Servopack Power

Symbol Import Procedure

Step	Instruction	Detail
1	Log On (Online or Offline)	Double-click CPU folder to log on. The default User Name and Password are both USER-A
2	Close everything except File Manager	Close Ladder Editor, Engineering Manager, etc
3	Open Symbol Manager	From File Manager, under Database folder, open Symbol Manager. Symbol Manager Application opens.
4	Open Symbol List	Under View menu, be sure Data Tree is checked. Expand Data Tree to open Symbol List and double-click All Register to open.
5	Import Symbols	Under File menu, choose Import. Locate desired *.CSV symbol file (such as MotionImport.csv) and open.
6	Save Symbols	Use the SAVE icon, CTRL-S, or File-Save. <i>It may take a few seconds for saving to complete, depending on the number of symbols in the project and the speed of the computer.</i>

Repeat process for additional symbol list *.CSV files

Serial & Ethernet Connection Procedure (To MPE720)

Serial Connection

Instruction	Step	Detail
Define the PC's Serial port as a valid way to communicate via MPE720	1	Connect serial cable from MP900 port 1 to PC's COM port.
	2	Open Communication manager from system tray
	3	Double click a "logical port number", choose "serial" and click "Detail"
	4	Choose desired "physical port" number that the serial cable is connected to on the PC.
	5	Save and close communication manager
	6	Restart MPE720

Ethernet Connection

First complete the MP900 Startup Procedure

MW/MPE720 communicates to the MP900's 218IF-01 Ethernet module through the Communication Manager program. All 3 must be configured to log on online over Ethernet.

Be sure the 218-IF TEST and INIT dipswitches are both off (right)

Instruction	Step	Detail
Give the 218IFmodule an IP address	1	Logged On, Online via serial port (CP-217)
	2	From file manager, under Definition folder, open Module Configuration.
	3	Select 218-IF. Highlight the column of 218IF-01 slot
	4	Double-click slot 2 (or R-click - Open Slot)
	5	Enter the IP address for the controller and save. (The table at the bottom of the screen is for other Ethernet devices controlled by the MP900).
	6	Cycle unit power (be sure only RUN dipswitch is ON on both the base unit and the 218IF-01 dipswitches are OFF to avoid overwriting upon power up)
Define the PC's Ethernet port as a valid way to communicate via MPE720	1	Open Communication Manager (from windows system tray, near clock)
	2	Double click a blank logical port to open the settings
	3	Choose CP-218 (scroll down), click detail
	4	Select the IP address of the PC.
	5	Turn "Default" to OFF
	6	Click "OK" twice, save, and close communication manager
	7	Close MW/MPE720, then re-open so that the data is refreshed
Tell MW/MPE720 to connect via Ethernet	1	Remain Logged Off
	2	R-click controller folder, choose properties Under Network tab, choose port number with CP-218 that you just made in
	3	Communication Manager
	4	Type the IP address of the controller, as defined in Module Configuration
	6	Log On, Online

NOTES:

It is assumed that a valid IP address has been acquired from the network administrator.
 To connect directly, use a crossover cable and configure your PC to use a static IP address.
 As noted on the 218IF module, the network must be 10mbps, or switchable from 100mbps to 10mbps.
 If a 218IF error does not go away after power is cycled, turn on the 218IF INIT dipswitch and cycle power.

MP920 Module Configuration

In general, when you are prompted with "save ok" or "new file", just click OK.

Open Module configuration - maximize the window

Under Slot Number 00, select MP920 and click SAVE. The hardware will appear in the STATUS field according to the slot it is located at.

Setup SVB-01

Choose module type "SVB-01" at the corresponding slot number

Specify IO range: Use Memory Map conventions - start at 100

Double click "Mechatrolink" in Details field

Select "IO assignment" tab. Choose the correct hardware (type) according to its corresponding rotary address switch (ST#), save and close

"Unsetting" appears in the SVB-01 Status. Save, cycle power, to clear. "Running" status appears

Open SVB - double click the SLOT NUMBER

Fixed Parameters Tab: Verify No.1, 3, 7. Save & Cycle power. Many of the other parameters only apply when the programming unit is changed from encoder pulses.

SERVOPACK Tab: Edit Menu choose "default set" and save. Over-Travels ARE wired on the demo.

If they are not wired, disable them in Pn50A and Pn50B and cycle power.

Setup Parameters Tab: Turn on the servo with OWC001 to test the configuration. Don't save anything here unless you want it to be the default on power-up. Use the Edit menu - Default Set and save to restore defaults.

Monitor Tab: Look at "feedback position" (No. 9 in the list) and move motor by hand to verify motor position

Repeat for each axis controlled by the SVB module. (select axis in upper left corner)

Setup LIO-01

Choose module type "LIO-01" at the corresponding slot number

Specify IO range: Use Memory Map conventions - start at 0

Open LIO - double click the SLOT NUMBER

Click "save" and the Current Value will update with the IO status. Test by monitoring inputs and setting outputs from this screen.

Set Scan Time

Definition Folder - Scan time setting

High Scan setting = 2 ms, Low Scan setting = 30 ms

Save

Setup SVA

Power Off. Remove option card & clear A.E7 with Fn014. Reset parameters with Fn005 & cycle power. Absolute encoder unplugged will produce A.81. Use Fn008, pressing ^ (arrow) to select PGCL5 and press Mode/Set. Then cycle power to clear the A.81.

Connect cable from desired SVA output CNx to SDGH IO connector CN1.

Wire overtravels or mask off with Pn50A.3 and Pn50B.0 using Digital Operator or SigmaWin+ & cycle power.

(On demo they are wired through the SVA cable)

Choose module type "SVA-01" at the corresponding slot number

Type a Circuit Number higher than any other SVA or SVB circuit

Save. "Unsetting" appears in SVA status. Save, cycle power and "running" status appears

Open SVA - doubleclick SLOT NUMBER

Check axis number and adjust according to number of connector used for servopack.

Fixed Parameters Tab: Check No.1, 3, 7. Many of the other parameters only apply when the programming unit is changed from encoder pulses.

Setup Parameters Tab: Turn on the servo with OWC001 to test the configuration. Don't save anything here unless you want it to be the default on power-up. Use the Edit menu - Default Set and save to restore defaults.

Monitor Tab: Look at "feedback position" (No. 9 in the list) and move motor by hand to verify motor position

Repeat for each axis under SVA control (select axis in upper left corner)

Basic Set of Registers for Register-Based Programming

Assume Module(Circuit) #1, Axis #1. Add 400h per circuit, 40h per axis.

Motion Setting Registers (OWxxxx)

Name	Word	Bit	[Unit] / Note	Reference
Servo On	OBC001	0		
Alarm Clear	OBC000	6		
Speed ("Feed" Speed)	OLC022		[10 ³ R.U./minute (by default)]	
Motion Command Code	OWC020		1=Position, 3=Home, 7=Jog, 8=Step	
Position Reference	OLC012		[R.U.]	
Abs/Inc Position Mode	OBC001	E	0=Abs, 1=Inc	
Step Distance	OLC028		[R.U.]	
Direction (Step,Jog)	OBC021	2	0=Fwd, 1=Rev	
Acceleration	OWC00C		[ms to rated speed (FP7)] SVB: Use OWC020=10 to send accel to servopack Pn80B	
Deceleration	OWC00D		[ms to rated speed (FP7)] SVB: Use OWC020=11 to send accel to servopack Pn80E	

Motion Monitoring Registers (IWxxxx)

Name	Word	Bit	[Unit] / Note	Reference
Servo Alarm	ILC022		=0 when no alarm. Each bit represents different alarm	
Mtn Cmd Code confirm	IWC014			
Main Power On	IBC001	4		
Servo On Confirm	IBC001	3		
Feedback Position	ILC008		[counts or Reference Units]	

Motion Command Code

Indexing Example

Move from position 5000 to position 8000, assuming the following for module (circuit) #1, Axis #1

ILC008=5000 Current position is 5000
ILC022=0 No alarms
IBC0013=1 Servo is ON

Solution using **STEP**

	OLC028=3000	Step Distance 3000
1	OBC0202=0	Direction Forward
	OLC022>=0	Set Feed Speed
2	OWC020=8	MtnCmdCd starts motion

Solution using **POSITION (INCRemental)**

	OLC012=0	Initial position 0
1	OBC001E=1	Incremental Positioning Mode
	OLC022>=0	Set Feed Speed
2	OWC020=1	MtnCmdCd defines initial position
3	OLC012=3000	Position reference incremented starts motion

Solution using **POSITION (ABSolute)**

	OBC001E=0	Absolute Positioning Mode
1	OLC022>=0	Set Feed Speed
	OWC012=8000	Position Reference to Absolute position
2	OWC020=1	MtnCmdCd starts Motion

Function Block Startup Procedure


First complete the MP900 Startup Procedure
A controller folder should already exist

Step	Instruction	Detail
1	Acquire project file	*.MAL extension Download to C:\ or any directory without spaces.
2	Log ON (online)	R-Click Controller folder, Log OFF. R-Click controller folder, check "online". Double-click Controller folder to log on. The default User Name and Password are both USER-A
3	Extract MAL file to controller files on hard drive	R-click Controller folder, Transfer, Selected Files, From Another Drive to MPE720. Find *.MAL file. *Check the FUNC box. Under "detail", be sure "select all" is checked. Then click "transfer" button. <i>Takes about 30 seconds.</i> Close window when complet
4	Transfer Function blocks to Controller*	R-Click controller folder, Transfer, Selected Files, From MPE720 to Controller. *Check the FUNC box. Under "detail", be sure "select all" is checked. Then click "transfer" button. <i>Transfer takes almost 4 minutes with serial connection.</i> Close window
5	Save to Flash	Optional. Click the Black Diskette Icon. When the window pops up, click the leftmost button (Compar/save) and accept other defaults. Close window when complete.
6	Cycle Power	Cycle power is needed for initialization drawings (A drawings) to run

* *To start a totally blank Function Block project, only check FUNC box and all detail. To start with the pre-made Function Block template, check both DWG and FUNC and under each detail select "all".*

Motion Program Startup Procedure

First complete the MP900 Commissioning Procedure
There should be a new controller folder



Group Definition (axes used in motion program)

Step	Instruction	Detail
1	Log on Offline	R-Click Controller folder and select Log Off. R-click again and uncheck "online". Double-click controller folder to log on
2	Open Group Definition	In File Manager-> Programs -> High Scan Programs -> Motion Programs -> DoubleClick "Group Definition"
3	Enter & Save a Group Name	Under the "Group List" Tab. When saved a new "Group01" tab will appear.
4	Enter the number of axes that will be used in the Motion Program	Under the "Group01" Tab, in the "Axis" area.
5	Define Module Number, Axis Number, and Axis Name	Under "Group01" Tab, in the "Axis Definition" area. In the "Physical" row, 01.01 means motion module 1, axis 1. Usually the default is fine. In the "Logical" row, enter a text name for the axis. X and Y are common.
6	Define Other Fields	Task: ____, Create Ladder Dwgs: OFF, Alarm Out: MW500, Shared Drawing: MW502
7	Save Group Definition	Save Icon
8	Log on Online	R-Click Controller folder and select Log Off. R-click again and check "online". Double-click controller folder to log on
9	Transfer Group Definition to Controller	In File Manager, R-click Controller folder, Transfer-> Selected Files-> From MPE720 to Controller. Check the box for "Group Definition" and click the Transfer button. Accept defaults.



	Axis01	Axis02
Physical	01.01	01.02
Logical	AXIS1	B1

Motion Program

Step	Instruction	Detail
1	Start a new Motion Program	In File Manager-> Programs -> High Scan Programs -> Motion Programs, R-click "Motion Group01" and select "New Program".
2	Things to know before a Motion Program is started	There are no commands for SERVO ON or JOG in the Motion Programming Language. These steps are to be accomplished in Ladder. First line must be 'MPM001' and last line must be 'END;'. Instructions terminate with semicolon. Comments enclosed in quotes ("comment"). Refer to Motion Programming User Manual (SIEZ-C887-1.3) for extensive details on each command.
3	Write Motion Program	
4	Save Motion Program	Use save icon. Also save to flash.

Call From Ladder

Step	Instruction	Detail
1	Use the MSEE instruction	MSEE is located under the "Motion" tab in Ladder Editor. It can only be used in an H-drawing. Define a starting address for the two 16-bit work registers in the Data field. Often DA00000 is used defining DW00000 through DW00003, but be sure to use M or
2	Rules before starting	All axes in the group must have: 1) Servo On, 2) Motion Command Code =0 and not continually updated to 0, 3) No other motion program in same group running, in alarm, or paused
3	Start the motion program	Bit 0 of the second word defined in the Data field (DB000010 in the above example) must go high for the motion program to start. See Motion Program Work Registers in this QRG for more information.
4	Rules while running	Ladder code must not manipulate Motion Command Code, unless motion language is not using the Motion Command Code register the time, and proper interlocks are used to flag the ladder code

Motion Program Work Registers for MSEE instruction

1st Work Register	OUTPUT (Motion Program Status)		
	DW00000		
	Bit	Name	Description
	DB000000	Program Running	ON while running
	DB000001	Program Paused	ON while paused
	DB000004	Program in Debug (Single Block) Mode	ON during debug via ladder (registers)
	DB000008	Program Alarm	ON when Motion Program Alarm has occurred
	DB00000B	Program Debugging Mode	ON during Windows (EWS) debug mode
	DB00000E	Program Duplication Error	ON when another Motion Program in the same group has started while this program is running
DB00000F	Program Number Limit Error	ON when the number of steps in program exceeded maximum	

2nd Work Register	INPUT (Motion Program Control Signals)		
	DW00001		
	Bit	Name	Description
	DB000010	Program Start Request	ON with rising edge. (if it CAN start it will, otherwise alarm)
	DB000011	Program Pause Request	ON will pause motion blocks
	DB000012	Program Stop Request	ON will stop all group motion, exit the Motion Program, and generate a motion program alarm
	DB000013	Program Debug Mode Select	"Single block mode". ON will force debugging mode
	DB000014	Program Debug Start	"Single Block Mode" start. ON (transition) debug block by block
	DB000015	Program alarm Reset	ON will clear the program alarm (stop program before issuing alarm reset)
DB000018	Block Skip 1 Operation	ON will cause the program to skip an interpolated motion block if the SKP ss1 instruction was used instead of MVS	
DB000019	Block Skip 2 Operation	ON will cause the program to skip an interpolated motion block if the SKP ss2 instruction was used instead of MVS	

INTERPOLATION OVERRIDE (Speed)	
MW00001	Interpolation speed set by F designation and IFP is scaled by the value in this register [units 0.01%].

SPEED OVERRIDE	
OW**2C	The speed set by the VEL command (OLC022) will be scaled by the value in OWC02C [units 0.01%] when Fixed Parameter 17, bit 9 =1.


Error Code Register	
MWxxxx (Defined in Group Definition)	See Section 8.2.2 in Motion Module Manual (SIE-887-2.5). To clear a motion program alarm: A. Determine and resolve the cause of the alarm (Alarm Register

Data Trace

Quick Method

Add registers to trace	R-Click in ladder, select "register to trace", or type registers manually. To graph speed, create it in ladder using position scan differential.
Save configuration	CTRL-S or from menu. The selected data starts filling the trace buffer (FIFO) immediately
Snap the data	Click the Snap button to display the data currently in the trace buffer. Click Snap AFTER the motion completes. Although the data displayed is fixed, data continues to fill the buffer.

Illustration



Notes

- By default, the data saved in the list is updated every H-scan
- The trace buffer is limited to 32,000 16-bit words per "group". Once it is full, old data is pushed out by the new data.
- Four (4) groups of trace data can be collected simultaneously.
- Set the trigger condition to capture an event, such as a fault, or to change sample rate.

Reference Units (User Units)

KEY
 * RU = "reference unit" = "user unit" = "command unit"
 * FP = Fixed Parameter
 * MCC = Motion Command Code (OWxx20)
 * Register Values given for Circuit#1, Axis#1
 * **Bold type** represents default setting

NOTES:
 * Register Addresses assume Circuit#1, Axis#1
 * Reference Units not compatible with Function Block programming.
 * Default Positioning units are [encoder pulses (post quad)]
 * Default Speed Reference units are [1000 pulses/min]
 * Default Accel/Decel units are [ms to rated motor rpm]
 * MPE720 5.31B "Units" in module configuration do not update
 * Motion Module Manual incorrectly lists MCC=11 and Decel (OLC00D) as not used

