

SERVICE MANUAL FOR

Varispeed-626MTII Drive

AC Adjustable Speed Drives for Machine Tools



SIE-S626-1.1

September 1982

REV ◊ July, 1983

This service manual covers Types CIMR-MT-7.5K through 22K of our machine tool spindle AC drive units VARISPEED-626MTII (VS-626MTII).

The VS-626MTII comprises a squirrel cage AC induction motor controlled by a vector-controlled inverter, making its performance comparable to a DC drive system. The VS-626MTII is designed to operate at high reliability in factory atmosphere, and requires only minimum maintenance service, which is described in this manual.

## CONTENTS

1. GENERAL REQUIREMENTS .....	3
1.1 OPERATING CONDITIONS .....	3
1.2 PERIODIC INSPECTION .....	3
1.3 GROUNDING .....	4
1.4 INSTRUMENTS AND TOOLS REQUIRED FOR MAINTENANCE .....	4
1.5 REPLACING PRINTED CIRCUIT BOARD .....	4
1.6 HANDLING POTENTIOMETER AND SHUNT CONNECTOR .....	5
2. CONFIGURATION .....	5
2.1 SYSTEM CONFIGURATION .....	6
2.2 INTERCHANGEABILITY OF CONTROL CIRCUIT .....	6
3. ADJUSTING POTENTIOMETERS AND SETTING SHUNT CONNECTORS .....	8
3.1 ADJUSTABLE POTENTIOMETERS .....	8
3.2 POTENTIOMETER PRESET AT FACTORY .....	8
3.3 SELECTABLE SHUNT CONNECTOR .....	10
3.4 NON-SELECTABLE SHUNT CONNECTOR .....	11
4. TROUBLESHOOTING .....	12
4.1 CHECKING SUPPLY VOLTAGE AND CAUTIONS IN TROUBLESHOOTING .....	12
4.2 TROUBLESHOOTING FLOW CHART .....	13
5. ORIENTATION (MAGNETIC SENSOR SYSTEM) .....	25
5.1 OUTLINE .....	25
5.2 CONFIGURATION .....	25
5.3 FUNCTION OF POTENTIOMETERS .....	26
5.4 DISPLAY OF LED .....	28
5.5 OUTLINE OF OPERATION .....	28
5.6 ADJUSTMENT .....	31
5.7 ORIENTATION TROUBLESHOOTING .....	33
APPENDIX .....	35

# 1. GENERAL REQUIREMENTS

## 1.1 OPERATING CONDITIONS

Operate the VS-626MTII under the following conditions.

- Ambient temperature: -10 to +55°C
- Relative humidity: 10 to 95% (non-condensing)
- Elevation: up to 1000 meters above sea level
- Frequency fluctuation: ±1% max.
- Power supply: See Table 1.1

Table 1.1 Permissible Voltage

Nominal voltage (V)	Frequency (Hz)	Permissible voltage (V)
200	50 or 60	180 to 220
220	50 or 60	187 to 242
240	60	192 to 252

Note: When the power supply voltage is in the 400 V range (nominal), use a transformer (optional).

## 1.2 PERIODIC INSPECTION

To maintain the VS-626MTII in good operating order, check it approximately once every 6 months, in accordance with Table 1.2.

Table 1.2 Periodic Inspection Items and Description

State		Item	Procedure	Criteria	Action
Run	Stop				
○		Power transistor cooling fan	Check for noise and vibration	Noise or vibration not present before	Contact Yaskawa representative.
	○*	Power transistor cooling fan and adjacent area	Visual check of parts around power transistor fan	Deposited dust	Clean with vacuum cleaner.
	○*	Terminal screws in VS-626MTII controller	Manual check of all mutual wiring terminal screws with Phillips screwdriver	Loose screws	Tighten.

Check marked with \* should be made approx. 10 minutes after turning off the power supply.

### 1.3 GROUNDING

- Connect the grounding wires for the power supply lines and the power lines connected to the controller to terminal E.
- Connect the grounding bolt of the controller to a single ground pole. Observe the following provisions of the official standards.

For 200 V circuit: Class 3 grounding

### 1.4 INSTRUMENTS AND TOOLS REQUIRED FOR MAINTENANCE


Table 1.3 Instruments and Tools for Maintenance

Type	Specification	Usage	
		Adjustment	Troubleshooting
Multimeter	—	○	○
Screwdriver and Phillips type screwdriver	Large, medium, small	○	○
Roundnose pliers	—	—	○
Socket wrench	13 mm	—	○

### 1.5 REPLACING PRINTED CIRCUIT BOARD

- Do not replace the printed circuit boards or plug or unplug the connectors with the power supply on, as this may damage circuit members. For the replacing producers, refer to APPENDIX 10 - 13.


## 1.6 HANDLING POTENTIOMETER AND SHUNT CONNECTOR



These digits are not displayed.

Adjustment of Potentiometer  
(Setting to "3" in shown)

Note: Do not adjust potentiometer locked with red enamel, as they are adjusted at the factory.



Selective setting of shunt connector (Setting to TEST is shown)

Note: Do not change the setting of shunt connectors for which setting has been specified before shipment. Set only those listed in Table 3.3 on page 10.

## 2. CONFIGURATION

### 2.1 SYSTEM CONFIGURATION

With the VS-626MTII, a machine tool spindle AC drive system is configured as shown in Fig. 2.1.




Fig. 2.1 VS-626MTII System Configuration

### 2.2 INTERCHANGEABILITY OF CONTROL CIRCUIT

The control circuit of the VS-626MTII is configured with printed circuit boards. Even if faulty boards are replaced, an adjusted control circuit does not need readjustment after board replacement. Adjustment is required only with potentiometers (Table 3.1) which are designed to be adapted to the usages by proper adjustment. Replace the printed circuit boards in accordance with Table 2.1.

Table 2.1 . Printed Circuit Board

VS-626MTII Type CIMR-MT-	Usage	Controller	Base driver	Motor card	Orientation card	Note
		Type	Type	Type	Type	
		( Code No. )	( Code No. )	( Code No. )	( Code No. )	
5.5 K	L	JPAC-C061 (ETC005812)	JPAC-C062 (ETC005820)	JPAC-C079 (ETC005990)	JPAC-C063 (ETC005830) (Option)	
5.5 K	MC			JPAC-C070 (ETC005900)		
7.5K	L			JPAC-C071 (ETC005910)		
7.5K	MC			JPAC-C072 (ETC005920)		
11K	L MC			JPAC-C073 (ETC005930)		
15K	L			JPAC-C074 (ETC005940)		
15K	MC			JPAC-C075 (ETC005950)		
18.5K	L MC			JPAC-C076 (ETC005960)		
22K	L MC			JPAC-C077 (ETC005970)		
26 K	L MC			JPAC-C078 (ETC005980)		

Note: L: Lathe (for foot-mounted motors)  
 MC: Machining center (for flange-mounted motors)

### 3. ADJUSTING POTENTIOMETERS AND SETTING SHUNT CONNECTORS

#### 3.1 ADJUSTMENT POTENTIOMETERS

Table 3.1 shows the potentiometers which are designed for adjustment to adapt to the operation specifications. For option, refer to Table 5.2 on page 25.

Table 3.1 Adjustable Potentiometers

Printed circuit board	Code	Description	Adjusting & characteristics
Controller	NREV	Reverse speed compensation	See APPENDIX 18.
	NADJ	Speed adjustment	
	NGAIN	Speed loop gain adjustment	See APPENDIX 14.
	TLIM	Torque limit level setting	See APPENDIX 15.
	SMADJ	Speedometer amplitude adjustment	See APPENDIX 19.
	LMADJ	Load meter amplitude adjustment	See APPENDIX 20.
	NDET	Speed coincidence detection level	See APPENDIX 16.
	TDET	Torque detection level	See APPENDIX 17.

#### 3.2 POTENTIOMETER PRESET AT FACTORY

Table 3.2 gives the potentiometers preset at the factory. They require special instruments for correct adjustment. Do not tamper with them unless under emergency conditions. They are marked by red enamel for distinction from other potentiometers.



Table 3.2 Potentiometer Preset at Factory

Printed circuit board	Code	Description	Standard setting value	Note
Controller	TMAX	Max. torque limit	See APPENDIX 22.	
	1RH	Slip frequency setting	Frequency of CH18 = 7.5 kHz $\pm$ 15Hz	<ul style="list-style-type: none"> <li>• 1 V at terminal ⑦, 2FC</li> <li>• 3 V at terminal ⑨, 2FC</li> <li>• Shunt connector I</li> </ul>
	2RH	Regeneration power limit	Voltage of CH5 $\dot{=}$ -3.6 to -11 V	See APPENDIX 15.
	3RH	Exciting current command level	CH5 or CH8 voltage of motor card = 2.5 Vp-p	Resolver detection frequency = 18.9 kHz Field weakening command = 0 V
	4RH	Regeneration voltage detection level	CH8 voltage = 3.15 V $\pm$ 0.1 V/340 VDC	DC main circuit voltage: VDC
	5RH	Current calculation carrier amplitude adjustment	CH6 voltage = Vp-p - 3 V $\pm$ 0.5 14 - 16.5 kHz	CH6 voltage waveform: triangular wave
	6RH	KIP pulse angle setting	Thyristor gate pulse control lag angle = 165° $\pm$ 4°	Regeneration state
	7RH	Regeneration voltage limit level	See APPENDIX 23.	
	8 - 10RH	Phase shifter lamp signal adjustment	Control lag angle $\alpha$ = (20° $\pm$ 7°) - (165° $\pm$ 4°)	Thyristor gate pulse observation
	11RH	Speed command offset	CH19 voltage  $\leq$ 3 mV	Speed command = 0 V
	12RH	Speed command limit level	CH19 voltage  $\leq$ (10.5 $\pm$ 0.2 V)	During override
	13RH	Acceleration/Deceleration time setting	CH19 voltage by 10 V step input to CH23 = 2 $\pm$ 0.2S	IDS: 2 sec selection
	14RH	Speed loop offset	CH4 voltage  $\leq$ .10 mV	Speed command: 0 NGAIN: max.
	15RH	Primary frequency amplitude adjustment	CH1, CH2 voltage peak = 3 $\pm$ 0.1 V	_____
	16RH	Speed detection level	CH22 voltage = -10 V $\pm$ 10 mV/6000rpm	Resolver detection frequency: 21.6 kHz

Table 3.2 Potentiometer Preset at Factory (Cont'd)

Printed circuit board	Code	Description	Standard setting value	Note
Con- trol- ler	17RH	Speed detection offset	$ \text{CH22 voltage}  = 10 \text{ mV}$	Resolver detection frequency: 18 kHz
	18RH	Resolver excitation balance adjustment	CH37 voltage = CH39 voltage	CH35, CH36 frequency = 18 kHz
Motor card	1RH	Overload operation level	Integration start current	Motor rated current (30 min) x 1.05
	2RH	Overload operation time	See APPENDIX 24.	
	3RH	Current loop offset ( $\alpha$ phase)	Motor DC current: 0.3 A or below	_____
	4RH	Current loop offset ( $\beta$ phase)	Motor DC current: 0.3 A or below	_____

### 3.3 SELECTABLE SHUNT CONNECTOR

Table 3.3 shows the selectable shunt connectors. Select them to suit required specifications.

Table 3.3 Selectable Shunt Connector

Printed circuit board	Function	Description				Note
Con- trol- ler	Speed standard selection	A	6000rpm	B	4500 rpm	Select in accordance with motor max. speed. Uniformly select for group of A, D, K and O, and group of B, C, L and P.
	Overspeed operation level	D	6000rpm	C	4500 rpm	
	Overspeed operation level	K	6000rpm	L	4500 rpm	
	Speed standard selection	O	6000rpm	P T	4500 rpm	
	50/60 Hz selection	M	50 Hz	N	60 Hz	Select by supply frequency.
	Fault display mode selection	G	In fault, 33 - 34 conductive in 1CN	H	In fault, 34 - 35 conductive in 1CN	Selection between normally on and normally off.

Table 3.3 Selectable Shunt Connector (Cont'd)

Printed circuit board	Function	Description				Note
		Q	D/A output signal	R	Analog signal	
Con-trol-ler	Speed command selection					Selection by speed command type

3.4 NON-SELECTABLE SHUNT CONNECTOR

Table 3.4 shows the shunt connectors which are preselected before shipment. They can not be reselected.

Table 3.4 Non-selectable Shunt Connectors

Printed circuit board	Function	Description				Note
Con-trol-ler	Low voltage operation level	E	Low	F	HI	—
	Slip frequency compensation	I	Speed compensation	J	Field weakening compensation	—
Motor card	PWM carrier modulation	A	Impossi-ble	B	Possible	—
Base-driver	OC detection level	A	Low	B	HI	—
	+18 V level	C	HI	D	Low	—
	-18 V level	E	HI	F	Low	—

#### 4. TROUBLESHOOTING

Paragraphs 4.1 and 4.2 describe the troubleshooting processes for VS-626MTII controller.

##### 4.1 CHECKING SUPPLY VOLTAGE AND CAUTIONS IN TROUBLESHOOTING

Before starting to troubleshoot check the supply voltage in accordance with Table 4.1. If the AC supply voltage is outside the permissible range, change the power supply. If the DC supply voltage is outside the permissible range, replace the controller.

The items in [ ] in the troubleshooting charts in paragraph 4.2 and subsequent paragraphs are adjusted before shipment, and should not be tampered with.

Table 4.1 Power Supply Voltage

Power supply	Permissible voltage range	Check point	Note	
AC	See Table 1.1 on page 3.	R, S, T terminals	—	
DC	+15 V	14.25 to 15.75 V	See stabilized power supply, APPENDIX 3.	
	-15 V	-14.25 to -15.75 V		
	+8 V	7.6 to 8.4 V		
	-8 V	-7.6 to -8.4 V		
	-8 V	-7.6 to -8.4 V		
	-3 V	-2.35 to -3.65 V		
	+30 V	25 to 29/V = 200 V 28 to 32/V = 220 V	Across CH25 - CH29	Non-stabilized power supply, VAC = Supply voltage
	-30 V	-25 to -29/V = 200 V -29 to -32/V = 220 V	Across CH34 - CH29	

Note: Check terminals CHs are provided on the controller.


#### 4.2 TROUBLESHOOTING FLOW CHART

Table 4.2 shows a list of trouble symptoms and the corresponding flow chart Nos.


Table 4.2 Trouble Symptoms

Trouble Symptom	Chart Ref.	Trouble Symptom	Chart Ref.
SOURCE does not light.	(1) on page 14.	OS lights.	(10) on page 19.
OH lights.	(2) on page 14.	UV lights.	(11) on page 20.
FANM lights.	(9) on page 18.	DEV lights.	(12) on page 20.
FANC lights.	(3) on page 15.	ZSP does not light.	(13) on page 21.
OV lights.	(4) on page 15.	AGREE does not light.	(14) on page 21.
OC lights.	(5) on page 16.	Motor does not run or does not accelerate.	(15) on page 22.
ACFU lights.	(6) on page 17.	Motor speed overshoots or fluctuates.	(16) on page 23.
DCFU lights.	(7) on page 17.	Excessive vibration and noise while running.	(17) on page 23.
OL lights.	(8) on page 18.	Too long acceleration. deceleration time.	(18) on page 24.
Orientation malfunctioned	See paragraph 5.7.	—	—


(1) SOURCE does not light.




(2) OH lights.




(3) FANC lights.



(4) OV lights.




(5) OC lights.







(6) ACFU lights.




(7) DCFU lights.




(8) OL lights.




(9) FANM lights.




(10) OS lights.




(11) UV lights.




(12) DEV lights.




(13) ZSP does not light.




(14) AGREE does not light.




(15) Motor does not run, or does not accelerate.




(16) Motor speed overshoots or is disturbed.



(17) Excessive vibration and noise while running



(18) Too long acceleration/deceleration time





## 5. ORIENTATION (MAGNETIC SENSOR SYSTEM)

### 5.1 OUTLINE

When the orientation card (JPAC-C063) and the spindle orientation detector (both options) are incorporated, the VS-626MTII is capable of controlling the angular position of the spindle. In this chapter, the adjustment and maintenance of the magnetic sensor type orientation system are described.

### 5.2 CONFIGURATION

Fig. 5.1 shows the configuration of the orientation system. Use the commercially available magneto and the magnetic sensors given in Table 5.1.




Fig. 5.1 Hardware Composition of Spindle Orientation System

Table 5.1 Magneto and Magnetic Sensor

Part Name	Type	Maker	Mounting Method
Magnet	MG-1378B MG-1378BS	Makome corporation	See APPENDIX 30 on page62
Magnet	MG-14444	Makome corporation	
Magnetic sensor	FSH-1378	Makome corporation	
Amplifier	FSD-1378	Makome corporation	
Magnetic sensor + amplifier	FS-200	Makome corporation	

### 5.3 FUNCTION OF POTENTIOMETERS AND SHUNT CONNECTOR

#### 5.3.1 Adjustable Potentiometers

Table 5.2 shows the potentiometers. Adjust them when adjusting the orientation performance.

Table 5.2 Adjustable Potentiometers

Printed circuit board	Code	Description	Adjusting method and characteristics
Orientation card	LEVEL	Adjustment of magnetic sensor output detection level	APPENDIX 32 on page 64.
	BIAS	Adjustment of stop position	APPENDIX 33 on page 65.
	H-GAIN	Adjustment of loop gain at H gear	APPENDIX 34 on page 66.
	M-GAIN	Adjustment of loop gain at M gear	APPENDIX 34 on page 66.
	L-GAIN	Adjustment of loop gain at L gear	APPENDIX 34 on page 66.
	H-TIME	Adjustment of deceleration time from orientation speed to creep speed at H-gear	APPENDIX 35 on page 66.
	L-TIME	Adjustment of deceleration time from orientation speed to creep speed at L gear	APPENDIX 36 on page 67.
	M-SPD	Adjustment of orientation speed at M gear	APPENDIX 38 on page 68.

Table 5.2 Adjustable Potentiometers (Cont'd)

Printed circuit board	Code	Description	Adjusting method and characteristics
Orientation card	L-SPD	Adjustment of orientation speed at L gear	APPENDIX 37 on page 67.
	FLD	Adjustment of field weakening command during orientation	APPENDIX 39 on page 69.

5.3.2 Potentiometers Adjusted Before Shipment

Table 5.3 shows the potentiometers which are adjusted before shipment. Do not tamper with these potentiometers as their adjustment require special instruments.

Table 5.3 Potentiometers Adjusted Before Shipment .

Printed circuit board	Code	Description	Standard setting value	Condition
Orientation card	F-OFS	Forward run offset adjustment	Orientation card CH6 voltage = 0 V	Magnetic sensor output = 0 V BIAS = 0 V
	R-OFS	Reverse run offset adjustment		

5.3.3 Selection of Shunt Connector Setting

Table 5.4 shows the selectable shunt connectors. Set them to the setting positions which are selected to suit to the specifications.



Table 5.4 Selectable Shunt Connector

Printed circuit board	Name	Description		Remarks
Orientation card	Run-test selection	TEST (Testing)	NORM (running)	
	Orientation speed selection	OR SPEED 1	Motor speed = 200 rpm	For selecting method, see APPENDIX 40 on page 70.
		OR SPEED 2	Motor speed = 300 rpm	
		OR SPEED 3	Motor speed = 400 rpm	

## 5.4 DISPLAY OF LED

Table 5.5 shows the information displayed by the LED lamps.

Table 5.5 Information Displayed by LED

Code	Color	Information
TEST MODE	Red	Keep lighting during test mode
LEVEL 1	Green	Lights when magnetic sensor output exceed set LEVEL 
LEVEL 2	Green	Lights when magnetic sensor output is below set LEVEL. 
CREEP	Green	Lights after running at creep speed for 200 ms, until LEVEL LED lights.
OR-END	Green	Lights when approx. 300 ms has lapsed after the entry of the spindle into INPOSITION FINE (for approx. $\pm 100 \mu\text{m}$ ).

Note:  $\pm 100 \mu\text{m}$  is measured on 120 mm dia. circumference.

## 5.5 OUTLINE OF OPERATION

### 5.5.1 Outline of Orientation Control

Fig. 5.2 shows the outline of orientation control system.




Fig. 5.2

### 5.5.2 Outline of Orientation Operation

Fig. 5.3 shows a time chart of orientation process.

The orientation operation is performed in the following sequence.

[WHEN NC GIVES ORIENTATION COMMAND]

- (1) At an orientation command, the speed controller shifts from PI to P position, and the spindle is decelerated (accelerated) to the orientation speed.
- (2) When the spindle speed becomes within  $\pm 15\%$  of the orientation speed, a speed coincidence signal is generated, and then, in 100 ms, a "LEVEL 1" signal is outputted and the soft starter in the orientation card decelerates spindle speed to the creep speed.
- (3) The spindle speed becomes lower than the creep speed, and 200 ms after, "CREEP" lamp is lighted to indicate the normal creep speed running condition.
- (4) At a "LEVEL 1" signal, "CREEP" goes out, and the control enters the orientation control mode, simultaneously outputting a field weakening command.
- (5) A zero speed signal is outputted near the stopping position, and in approximately 100 ms, the position gain is shifted from P to PI.
- (6) In 200 ms after the generation of an "INPOSITION FINE" signal, "OR-END" lights, and simultaneously, creep speed is cleared.




Fig. 5.3 Operation Time Chart


While OREND is on, the control is in the servo-clamp mode, and the speed remains within the IN POSITION FINE range even when external force is applied. If the speed goes out of this speed range, OREND goes out.


[TEST MODE]

- (1) At an orientation command from the NC, the spindle stops (zero speed).
- (2) When the TEST MODE button is pushed, the spindle starts to run at the orientation speed.
- (3) When the button is released, the same operation as [WHEN NC GIVES ORIENTATION COMMAND] is performed.

5.6 ADJUSTMENT

Adjust the system in accordance with the flow chart below.









## 5.7 ORIENTATION TROUBLESHOOTING

Here, main troubles and their causes are described. Locate and remedy troubles in accordance with the following flow chart.


(1) Spindle does not stop.




(2) Spindle stops, but repeating accuracy is low.




(3) "OR-END" does not light.




# APPENDIX 1 COMPONENT INTERCONNECTION DIAGRAM



APPENDIX 2 UNIT CONFIGURATION DRAWINGS



APPENDIX 3 VS-626MTII CONTROL SCHEMATIC DIAGRAM




APPENDIX 4 MAIN ELEMENT LIST


Parts	Type	CIMR-MTII -5.5K, -7.5K	CIMR-MTII -11K	CIMR-MTII -15K	CIMR-MTII -18.5K	CIMR-MTII -22K
Transistor module (11 - 13TRM)		MG100G1AL2		EVK71-050		EVL31-050
		STR141		STR142		STR143
Transistor module (17, 27, 37TRM)		EVK71-050	EVL31-050	---	EVK71-050	
		STR142	STR143	---	SCR142	
Thyristor module (1 - 3THM)		TM55DZ-H			TM90DZ-H	
		SCR197			SCR198	
Diode module (11 - 22DM)		RM60C2Z-H				
		SID304				
Fuse (1FU, 2FU)		25SH75	25SH100		25SH150	
		FU696	FU697		FU699	
Fuse (3FU)		25SH75	25SH100	25SH125	25SH150	25SH200
		FU696	FU697	FU698	FU699	FU700
Fuse (4FU, 5FU)		F-7161				
		FU383				
Capacitor (1 - 4C)		PWM2A2W222A				
		C2615				
AC reactor (ACX)		UZBA-B	UZBA-B	UZBA-B	UZBA-B	UZBA-B
		X 2468	X 2469	X 2470	X 2471	X 2472
Resistor (1R, 2R)		---	---	---	---	---
		R 2378	R 2383	R 2382		R 2381
Resistor (3R)		40SHS	40SHS	40SHS		
		R 2386	R 2385	R 2384		
Resistor (11R, 12R)		40SHS	40SHS	40SHS		40SHS
		R 2388	R 2389	R 2388		R 2387
Surge absorber (1 - 3SA)		TNR-15G471K				
		XX139				
Control power transformer (1T)		ZBC-20				
		CPT5767				
Cooling fan (1FAN)		EP145E				
		FAN93				
Snubber card (4PCB)		ETX193X				
Controller (1PCB)		JPAC-C061				
		ETC581X				
Base driver (2PCB)		JPAC-C062				
		ETC582X				
Motor card* (3PCB)		---				

\* Motor card varies with motor type and capacities. See Table 2.1 on page 7.


APPENDIX 5 UNIT LAYOUT

5-1) CIMR-MTII-7.5K











5-4) CIMR-MTII-18.5K, CIMR-MTII-22K




# APPENDIX 6 CONTROL BOARD PARTS LAYOUT

- ⊕ --- CHECK TERMINALS
- ⊙ --- DISPLAY LED
- ⊠ --- POTENTIOMETERS
- ⊡ --- SHUNT CONNECTOR




# APPENDIX 7 BASE DRIVE BOARD PARTS LAYOUT

⊕ --- CHECK TERMINALS  
 { --- SHUNT CONNECTOR




# APPENDIX 8-1 MOTOR CARD BOARD PARTS LAYOUT

- ⊕ --- CHECK TERMINALS
- ⊗ --- POTENTIOMETERS
- ⊞ --- SHUNT CONNECTOR



# APPENDIX 8-2 ORIENTATION BOARD PARTS LAYOUT

- ⊕ --- CHECK TERMINALS
- ⊗ --- DISPLAY LED
- ⊞ --- POTENTIOMETERS
- ⊞ --- SHUNT CONNECTOR



MAGNETIC SENSOR SIGNAL CONNECTOR


# APPENDIX 9 FUSE REPLACEMENT PROCEDURE

To replace fuses 1FU, 2FU, 3FU, 4FU, and 5FU in the unit, the board frame of the unit must be opened, as shown below.


CIMR-MTII-7.5K

CIMR-MTII-11K    CIMR-MTII-22K

BOARD FRAME



Unscrew one each screw on the top and bottom, and open the board frame towards left back.



Unscrew one each screw on the top and bottom, and open the board frame towards left back.

## APPENDIX 10 REPLACING CONTROL BOARD (PCB)

### (1) Dismounting printed circuit board

Procedures	Description
1	Turn off the power supply and disconnect the cable from the board.
2	Unscrew four screws mounting the printed circuit board (PCB), hold the heads of the four PCB supports with round-nose pliers, and remove the supports from the guide holes in the PCB.
3	Holding the PCB at the top and the bottom by hand, lift it and dismount it.

4-M4 MTG SCREWS  
PCB SUPPORT (4 LOCATIONS)  
PULL UPWARD TO DISMOUNT  
PCB SUPPORT  
PC BOARD

Note: Where the orientation board is mounted, dismount it by the orientation dismounting procedure (APPENDIX 13), and then, dismount the control board as described above.

### (2) Remounting printed circuit board

Procedures	Description
1	Push the four PCB supports through the guide holes in the PCB until it comes fully to the checking groove in the supports.
2	Secure the PCB to the board frame with screws at 4 positions.
3	Connect the cables to the connectors.
4	Check the setting of the PCB, and start operation.

INSERT LEVEL CHECKING GROOVE  
PCB SUPPORT

## APPENDIX 11 REPLACING BASE DRIVE BOARD (The board is mounted on the reverse side of the board frame.)

### (1) Dismounting board

Procedures	Description
1	Turn off the power supply and disconnect the cables from the board, by opening the board frame.
2	Dismount the board in the same way as for the control board.

(2) Remounting board

Remount the base drive board in the same way as with the control board.

APPENDIX 12 REPLACING MOTOR CARD BOARD

(1) Dismounting board

Procedures	Description
1	Turn off the power supply, and disconnect the cables (flat cables) from the board.
2	Holding the heads of the four PCB supports with a suitable tool such as round nose pliers, remove the supports from the guide holes in the board, and dismount the board.

(2) Remounting board

Procedures	Description
1	Insert the PCB supports through the guide holes in the board. Insert them to the same depth as for APPENDIX 10, (2), procedure 1.
2	Reconnect the cables to the connectors.
3	Check the setting of the board, and start operation.

APPENDIX 13 REPLACING ORIENTATION BOARD

(1) Dismounting board

Procedures	Description
1	Turn off the power supply, and disconnect the cables from the board.
2	Unscrew the five mounting screws.

(2) Remounting board

Remount the board by reversing the dismantling procedure (1), check the setting, and start operation.



## APPENDIX 14 ADJUSTING NGAIN

**ADJUSTMENT OBJECTIVE:** Adjusting loop gain of speed control system

**ADJUSTMENT PROCEDURE:** The more the setting is brought near the 0 graduation, the lower and stabler the gain becomes, but the slower becomes response. The nearer the setting is adjusted, the quicker becomes response, but larger becomes speed overshooting. Adjust it to the optimum gain taking into consideration of the load conditions.


**ADJUSTMENT BEFORE SHIPMENT:** Graduation 5

## APPENDIX 15 ADJUSTING TLIM

**ADJUSTMENT OBJECTIVE:** Adjusting maximum torque of motor

In this case, the motor operates at the lowest torque among max. torque limit  $T_1$ , limit value  $T_2$  by TLIM, and torque limit  $T_3$  for regeneration braking, as shown in Fig. 15.1. In the case of Fig. 15.1, the motor operates at  $T_2$ .

**ADJUSTMENT PROCEDURE:** The TLIM characteristics are as shown in Fig. 15.2. Set the potentiometer by the graduations using Fig. 15.2, or set it by means of the CH5 voltage.



$N_1$ : Max. speed 100%: 4500 rpm  
100%: 6000 rpm

$T_1$ : Max. torque limit = 120% (fixed)  
100% = 30 minute rated output torque

$T_2$ : Adjustment by TLIM, see Fig. 15.2.

$T_3$ : Regeneration torque limit (fixed)

Fig. 15.1 Speed-torque Limit Characteristics




Fig. 15.2 TLIM Characteristics

#### APPENDIX 16 ADJUSTING NDET

ADJUSTMENT OBJECTIVE: Adjustment of speed coincidence detection level

ADJUSTMENT PROCEDURE: While the motor speed is adjusted with speed commands, NDET lights at a certain speed which is adjusted with the NDET potentiometer. Adjust the NDET potentiometer so that the NDET LED lights at the intended goal speed, by referring to Fig. 16.




Fig. 16 NDET Characteristics

## APPENDIX 17 ADJUSTING TDET

ADJUSTMENT OBJECTIVE: Setting torque detection level

ADJUSTMENT PROCEDURE: Adjust the TLIM potentiometer by the method described in APPENDIX 15 to the torque detection level. Then, while accelerating the motor, adjust the TDET potentiometer so that the TDET LED lights at the required level.




Fig. 17 TDET Characteristics

## APPENDIX 18 ADJUSTING NADJ AND NREV

ADJUSTMENT OBJECTIVE: Coincidence between speed command input (CH23 voltage) and motor speed (speed command level).

ADJUSTMENT PROCEDURE I:

1. Cancel the override mode.
2. Supply 10 V input voltage to the CH23 terminal by analog speed command voltage (with the shunt connector of the controller set to R) or a D/A converter output (with the shunt connector of the controller set to Q).
3. Give a forward run command.
4. Set the NADJ potentiometer so that the CH19 voltage becomes the standard level of  $10 \pm 0.01$  V. or other required level.
5. Cancel the forward run command, and give a reverse run command.
6. Adjust the NREV potentiometer until the CH19 voltage becomes the standard level of  $-10 \pm 0.01$  V.

**ADJUSTMENT  
PROCEDURE II:**

Where the speed command input voltage is in both polarities, make adjustment as PROCEDURE I above, using only a forward run command.

**ADJUSTMENT  
PROCEDURE III:**

When setting the motor speed, make adjustment as described in I and II above so that with no-load and with the speed command input voltage at 10 V, the standard command input voltage at 10 V, the standard speeds of  $4500 \pm 45$  rpm and  $6000 \pm 60$  rpm become the required speeds.




Fig. 18 NADJ, NREV Adjustment Characteristics

**APPENDIX 19 ADJUSTING SMADJ**

**ADJUSTMENT OBJECTIVE:** Coincidence between speedometer reading and actual speed

**ADJUSTMENT PROCEDURE:** With the motor driven at the maximum speed, detect the speed with a tachometer, and adjust the speedometer pointer to the tachometer reading.

**APPENDIX 20 ADJUSTING LMADJ**

**ADJUSTMENT OBJECTIVE:** Conformance between torque command voltage and load meter reading.

**ADJUSTMENT PROCEDURE:** At the factory, the LMADJ potentiometer is adjusted so that at a motor output of 120% of the 30-minute rated power, 1 mA flowed through a load meter (ammeter) with an internal resistance of 2 k $\Omega$ . Therefore, no readjustment is required for a load meter with a scale graduated up to 1 mA. When adjusting the LMADJ potentiometer for some reasons, first cancel TLIM, and adjust the load meter reading to 120% of the 30-minute rated power during acceleration.

## APPENDIX 21 SOFT START CHARACTERISTICS

The soft start time is the sum of the numerals indicated by the DIP switches in seconds.




Fig. 21 Soft Start Characteristics

## APPENDIX 22 ADJUSTING TMAX

**ADJUSTMENT OBJECTIVE:** Setting the maximum torque command level to 120% of the 30-minute rating

**ADJUSTMENT PROCEDURE:** With the motor and the resolver disconnected, give the maximum speed command, and adjust the CH4 voltage as shown in Fig. 22.




Fig. 22 TMAX Characteristic

APPENDIX 23 SETTING 7RH

ADJUSTMENT OBJECTIVE: Setting regeneration starting voltage

ADJUSTMENT PROCEDURE: With the supply voltage at 220 V, set the CH14 voltage to 2.68 V




Fig. 23 Regeneration Characteristics

## APPENDIX 24 ADJUSTING MOTOR CARD 2RH

ADJUSTMENT OBJECTIVE: Setting time limit characteristics of OL

ADJUSTMENT PROCEDURE: Set the OL operation time with 2RH of the motor card.




Fig. 24 OL Operation Time Example

## APPENDIX 25 BASE BLOCKED CONDITIONS

Case	Description
1	Alarm red LED lights. (If OH, FANM, FANC, OV, OC, ACFU, DCFU, OL, OS, or UV operates.)
2	READY signal (RUNSB) is off.
3	Emergency stop signal (EMSTP) is on and motor standing still.
4	Forward run signal (FORRN) and reverse signal (REVRN) are both fed simultaneously, and the motor is standing still.

APPENDIX 26 LIGHTING CONDITIONS OF SOURCE AND RUN LEDS

Table 26 Lighting Conditions of SOURCE and RUN LEDs

Operation ready (STB)	Forward run command (FRN)	Reverse run command (RRN)	Emergency stop (EST)	LED		Note
				SOURCE	RUN	
X	X	X	X	X	X	During emergency stop
O	X	X	X	O	X	
X	O	X	X	X	X	
O	O	X	X	O	X	
X	X	O	X	X	X	
O	X	O	X	O	X	
X	O	O	X	X	X	
O	O	O	X	O	X	
X	X	X	O	X	X	—
O	X	X	O	O	X	Operation ready
X	O	X	O	X	X	—
O	O	X	O	O	O	Forward run
X	X	O	O	X	X	—
O	X	O	O	O	O	Reverse run
X	O	O	O	X	X	—
O	O	O	O	O	X	With forward and reverse commands are simultaneous fed, motor stops.

O: LED on  
X: LED off



APPENDIX 27 LIGHTING CONDITIONS FOR LEDS ON CONTROLLER

LED code	Color	Lighting conditions
NDET	Green	Attaining goal speed
ZSP	Green	Zero speed
AGREE	Green	Speed coincidence
DEV	Red	Excessive speed deviation
TDET	Green	Torque detection
SOURCE	Green	Power supply on
RUN	Green	Motor running
OH	Red	Tripping of built-in thermostat, and base blocked.
FANM	Red	Tripping of cooling fan thermal relay, base blocked.
FANC	Red	Malfunction of control cooling fan, and base blocked.
OV	Red	DC bus overvoltage and base blocked.
OC	Red	Transistor instantaneous overcurrent and base blocked.
ACFU	Red	AC fuse blowing and base blocked.
DCFU	Red	DC circuit fuse blowing and base blocked.
OL	Red	60 seconds 120% of 30-minute rated current, and base blocked.
OS	Red	110% ( $\pm 5\%$ ) rated speed or above and base blocked.
UV	Red	Supply voltage below 165 V ( $\pm 10$ V) and base blocked.

Note: When any of the LEDs OH through UV is on, the state is kept until the reset button on the controller is pushed, or reset by an external signal.

APPENDIX 28 CHECK TERMINALS AND THEIR SIGNALS

Table 28 Check Terminals and Their Signals













Printed circuit board	Check terminal	Content	Signal		Note
			At stop command (Ready ON)	In operation	
Control- ler	Across CH1-CH29	Primary frequency command ( $\alpha$ )	0 Hz	Frequency = (motor speed/30) + (3 to 4) Hz	—
	Across CH2-CH29	Primary frequency command ( $\beta$ )	Peak = $3 \pm 0.1$ V	Peak = $3 \pm 0.1$ V	—
	Across CH3-CH29	PWM carrier	3 kHz $\pm 0.3$ kHz 	Same as left	—
	Across CH4-CH29	Secondary current command	Within $\pm 10$ mV DC	DC, proportional to torque.	TMAX = $\pm 4$ V/ $\pm 100\%$
	Across CH5-CH29	Torque limit level	-1.4 to -7.53 V	Same as left	Change by TLIM setting
	Across CH6-CH29	Current calculation carrier		Same as left	—
	Across CH7-CH29	Regeneration transistor base signal		Same as left	60°el: DC source electric angle
	Across CH8-CH29	DC voltage	0 V	VDC x 0.09 V	VDC: Main circuit DC voltage
	Across CH9-CH29	DC voltage	0 V	(-6 $\pm$ 0.06) V/356 VDC	
	Across CH10-CH29	Phase shifter command	Kip: 5.6 V $\alpha$ limit: 0.5 V	Same as left	—
	Across CH11-CH29	Torque monitor	0 V	3.92 V/100% torque	CH11 voltage = 0 when motor current = 0
	Across CH12-CH29	Speed detection level (absolute)	0 V	10 V/ $\pm 6000$ rpm	—
	Across CH13-CH29	Field current command	3 V	0 V	Max. weakening at 3 V (weak during stop)
	Across CH14-CH29	Regeneration voltage standard	(2.68 $\pm$ 0.03) V/220 VAC	Same as left	VDC = AC source voltage
	Across CH15-CH29	Synchronous power supply (T phase)	24 $\pm$ 0.5V/220 VAC	Same as left	
	Across CH16-CH29	Synchronous power supply (S phase)			
	Across CH17-CH29	Synchronous power supply (R phase)			
	Across CH18-CH29	Slip frequency	+8 V  0.95 kHz -8 V	+8 V  -8 V	Changing with torque command
	Across CH19-CH29	Soft start output	0 V	See APPENDIX 21.	—
	Across CH20-CH29	Acceleration/deceleration level	0 V	$\pm 8$ V during acceleration/deceleration	—
	Across CH21-CH29	Acceleration deceleration signal	0 V		—

Table 28 Check Terminals and Their Signals (Cont'd)

Printed circuit board	Check terminal	Content	Signal		Note
			At stop command (Ready ON)	In operation	
Control- ler	Across CH22-CH29	Speed detection	0 V	-10 V/6000 rpm	—
	Across CH23-CH29	Speed command	Equal to external speed command level		10 V/4500 rpm, 10 V/6000 rpm
	Across CH24-CH29	Resolver output	18 kHz $\pm 0.67$ V	Frequency changes with speed	Sinusoidal
	Across CH35-CH29	Resolver exciting command ( $\beta$ phase)		Same as left	—
	Across CH36-CH29	Resolver exciting command ( $\alpha$ phase)			
	Across CH37-CH38	Resolver excitation ( $\alpha$ phase)		Same as left	—
	Across CH39-CH38	Resolver excitation ( $\beta$ phase)			
Base driver	Across CH1-CH7	Current detection (U phase)	$\pm 60$ mV or below		Frequency and amplitude change with operation condition.
	Across CH2-CH7	Current detection (W phase)			
	Across CH12-CH11	Regeneration transistor base signal input	-2 V		Generated during regeneration braking.
	Across CH14-CH13				
	Across CH16-CH15	Voltage between base of main transistor base current amplifying transistor and emitter of main transistor	-2 V		t changes with output current.
	Across CH18-CH17				
	Across CH20-CH19				
Across CH22-CH21					
Across CH24-CH23					
Across CH26-CH22					
Motor card	Across CH1-CH4	Field weakening command	$1.7 \pm 0.1$ V	Changing with speed.	—
	Across CH2-CH4	PWM carrier command	$3.0 \pm 0.15$ V		—
	Across CH3-CH4	Slip frequency (amplitude)	$3.0 \pm 0.15$ V		3 V/100%
	Across CH5-CH4	Field current command ( $\alpha$ phase)	0 V		Changing with speed.
	Across CH8-CH4	Field current command ( $\beta$ phase)			
	Across CH6-CH4	Torque current command ( $\alpha$ phase)	0 V		Changing with speed and torque. Phase depends on torque direction.
	Across CH7-CH4	Torque current command ( $\beta$ phase)			
	Across CH9-CH4	Primary current detection (W phase)	$\pm 60$ mV or below	Same as CH1, CH2 of base driver.	—
Across CH10-CH4	Primary current detection (U phase)				

## APPENDIX 29 CHECKING POWER SEMICONDUCTOR ELEMENTS

Turn off the AC power supply, and disconnect the motor leads from the inverter output terminals U, V and W. Disconnect lead wires from the respective transistor modules, thyristor modules, and diode modules, and measure their resistance with a multimeter. Evaluate these elements by the resistance values by comparing them with the values given in Table 29-1, 29-2 and 29-3.




Fig. 29 Terminal Layout of Power Modules


Table 29-1 Resistance of Transistor Modules

Transistor Module Terminals		Reference Resistance	Abnormal Resistance	Transistor Module
Tester Terminal (-)	Tester Terminal (+)			
E1C2	C1	*	0 Ω	
C1	E1C2	†	0 Ω	
B1	E1C2	*	#	
E1C2	B1	‡	0 Ω or ∞	
E2	E1C2	*	0 Ω	
E1C2	E2	†	0 Ω	
B2	E2	*	#	
E2	B2	‡	0 Ω or ∞	

\* Approximate multiple of 10 Ω      # Approximate multiple of 10 kΩ  
 † Several hundred of 1 kΩ      ‡ Several hundred Ω to several kΩ


Note: Use the tester set at x 1 Ω range.

Table 29-2 Resistance of Diode Module

Tester Terminals	⊖	⊕	Reference Resistance	Abnormal Resistance
Diode Module Terminals 	①	②	∞	Approximate multiple of 10 Ω or below
	①	③		
	②	①	Approximate multiple of 10 Ω or below	∞
	③	①		

Note: Use the tester set at x 1 Ω range.

Table 29-3 Resistance of Thyristor Module


Tester Terminals	⊖	⊕	Reference Resistance	Abnormal Resistance
Thyristor Module Terminals 	①	②	∞	Approximate multiple of 10 Ω or below
	③	①		
	②	①		
	①	③		
	②	G1	*	Other than *
	①	G2		
	G1	②	†	Other than †
	G2	①		

\* Approximate multiple of 10 Ω to several hundred Ω

† Several Ω to two hundred Ω

## APPENDIX 30 INSTALLING MAGNETO AND MAGNETIC SENSOR

Install magneto directly on the spindle as shown below. Install magnetic sensors on a stationary member, in such a way that at the tool change orientation of the spindle (fixed orientation), the center line of the magnetic sensor is aligned with the center line of the magneto.



Gap L: Varies with type of magneto (Spindle diameter: 120 - 140 mm)

Type	Recommended value	Permissible range (Approx. value)	
MG-1378	6 ± 0.5 mm	6 - 8 mm	} Range within which orientation detection signal level can be adjusted.
MG-1444	5 ± 0.5 mm	3 - 7 mm	

Gap ΔL: Should be 1 mm or above.

Misalignment between magneto and magnetic sensor ΔS1, ΔS2: 0.5 mm or below


Fig. 30 Installing Magneto and Magnetic Sensor

### CAUTIONS IN INSTALLATION

1. The spindle diameter must be 120 to 140 mm.
2. Do not bring units that generate magnetic fields such as solenoids and magnets near the magneto.
3. Take care to prevent iron powder from depositing on magneto.
4. Take care not to mechanically damage magnetic sensor heads and magneto.


MAGNETIC SENSOR

Type: FS-200.A (Made by MAKOME Corporation.)



MAGNETO

Type: MG-1378 (Made by MAKOME Corporation)



# APPENDIX 31 ORIENTATION CARD CHECK TERMINALS AND THEIR SIGNALS

Table 31 Orientation Card Check Terminals

Check terminal No.	Content	Signal level
CH1	0V (power supply)	—
CH2	Sensor position signal	Peak: $\pm 10$ V
CH3	Position deviation	0.4 V/100 $\mu$ m (on 12 mm diameter circumference)
CH4	Motor speed command (1)	-1 V/300 rpm
CH5	Motor speed command (2) (Switching from orientation speed to creep speed)	1 V/300 rpm
CH6	Motor speed command (Final stage)	0.5 V/300 rpm
CH7	Orientation signal and speed coincidence signal	H: +8 V L: -8 V
CH8	Position gain switching	H: +8 V L: -8 V

Note: For check terminal positions, see APPENDIX 8-2.

## APPENDIX 32 ADJUSTING LEVEL

ADJUSTMENT OBJECTIVE: Adjusting magnetic sensor output detection level

ADJUSTMENT PROCEDURE: Set the LEVEL potentiometer to the 0 graduation. With the spindle running, turn the LEVEL potentiometer clockwise and set it where both LEVEL 1 and LEVEL 2 LEDs start to light distinctly. Do not turn the LEVEL potentiometer further, because doing so will cause overadjustment. If the LEVEL 1 and LEVEL 2 LEDs do not light in this sequence, reverse the mounting direction of the magneto.







Fig. 32 LEVEL Characteristics

APPENDIX 33 ADJUSTING BIAS

ADJUSTMENT OBJECTIVE: Stop position fine adjustment

ADJUSTMENT PROCEDURE: See Fig. 33.



Note: Stop position is on 120 mm diameter circumference

Fig. 33 BIAS Characteristics

## APPENDIX 34 ADJUSTING H-GAIN, M-GAIN, L-GAIN

ADJUSTMENT OBJECTIVE: Adjustment of loop gain for orientation control

ADJUSTMENT PROCEDURE: Adjust the gain high as long as position control does not hunt. (CW turning)

## APPENDIX 35 ADJUSTING H.TIME

ADJUSTMENT OBJECTIVE: Adjustment of orientation time with VS-626MTII gear set to H or M.

ADJUSTMENT PROCEDURE: Set the H TIME potentiometer to 0 graduation. Push the button for approximately 3 seconds in the test mode, and then release it. While turning the H TIME potentiometer clockwise, repeat the orientation operation until the CREEP LED lights distinctly and the lighting time becomes shortest.

Note: When the gear is set to M, first adjust the spindle speed to 300 rpm with the M-SPD potentiometer, and then, adjust H TIME potentiometer.




Fig. 35 H TIME Adjusting Characteristics

## APPENDIX 36 ADJUSTING L TIME

**ADJUSTMENT OBJECTIVE:** Adjustment of orientation time when VS-626MTII is set to L gear.

**ADJUSTMENT PROCEDURE:** After setting the L TIME potentiometer to 0 graduation, adjust the spindle speed to 300 rpm with L-SPD. While turning the L TIME potentiometer clockwise in the test mode, push the button for approximately 3 seconds, and release, and repeat the orientation operation until the CREEP LED lights distinctly, and the lighting time becomes shortest.




Fig. 36 L TIME Characteristics

## APPENDIX 37 ADJUSTING L-SPD

**ADJUSTMENT OBJECTIVE:** Adjustment of orientation speed when VS-626MTII is set to L gear

**ADJUSTMENT PROCEDURE:** Set the L-SPD potentiometer to 0 graduation. With the VS-626MTII gear selection at L GEAR and in the test mode, push the button, and set L-SPD potentiometer until the spindle speed becomes 300 rpm at a CH4 voltage below 5.5 V. If the CH4 voltage is above 5.5 V, change the gear selection of VS-626MTII.

Note: Spindle speed (rpm) =  $\frac{\text{CH4 voltage (V)} \times 300}{\text{L gear ratio}}$

Gear ratio =  $\frac{\text{Spindle speed}}{\text{Motor speed}}$




Fig. 37 L-SPD Characteristics

#### APPENDIX 38 ADJUSTING M-SPD

- ADJUSTMENT OBJECTIVE:
- (1) Adjustment of orientation when VS-626MTII gear selection is H and M
  - (2) Orientation when VS-626MTII gear selection is only M

- ADJUSTMENT PROCEDURE: (1) Adjusting speed

After adjusting H TIME, set the M-SPD potentiometer to the 0 graduation. With VS-626MTII gear selection at M GEAR and in the test mode, push the button for 3 or so seconds and release, and then, repeat orientation operation until while turning M-SPD clockwise until the CREEP LED lights distinctly and the lighting time becomes the shortest. Push the button upon the final setting to make sure that the CH4 voltage does not exceed 5.5 V. If it is above 5.5 V, change the gear selection of VS-626MTII.

- (2) With VS-626MTII gear selection at M GEAR and in the test mode, push the button, and adjust the spindle speed to 300 rpm with the M-SPD potentiometer.




Fig. 38 M-SPD Characteristics

#### APPENDIX 39 ADJUSTING FLD

**ADJUSTMENT OBJECTIVE:** Depressing gear noise and smoothen low speed running by controlling the motor field current during orientation control.

**ADJUSTMENT PROCEDURE:** If gear noise is large and motor running is not smooth during orientation operation, turn the FLD potentiometer clockwise to reduce the field current.




Fig. 39 FLD Characteristics

## APPENDIX 40 ORIENTATION SPEED SELECTION METHOD

Select the orientation speed (OR SPEED) as shown in Tables 40.1 through 40.3 in accordance with the gear ratio and the gear stage. Apply the same method when the spindle is driven by belts.

### (1) Stage 1st gear

Table 40.1 OR SPEED Selection for Stage 1st Gear

Gear ratio = $\frac{\text{Spindle speed}}{\text{Motor speed}}$	OR SPEED selection	VS-626MTII gear selection (Wiring)
1.5 - 1.2	1	H GEAR (M GEAR OFF L GEAR OFF on page 35)
1.1 - 0.9	2	
0.8 - 0.6	3	
0.6 - 0.15	2	M GEAR (M GEAR ON on page 35)
0.2 - 0.05	1	L GEAR (L GEAR ON on page 35)

### (2) Stage 2nd gear

Table 40.2 OR SPEED Selection for Stage 2nd Gear

H gear ratio = $\frac{\text{Spindle speed}}{\text{Motor speed}}$	OR SPEED selection	VS-626MTII gear selection (Wiring)
1.5 - 1.2	1	If L gear ratio = 0.15 - 0.6, select M GEAR (M GEAR ON on page 34).
1.1 - 0.9	2	
0.8 - 0.6	3	If L gear ratio = 0.05 - 0.2, select L GEAR (L GEAR ON on page 35).

[EXAMPLE; Stage 2nd gear]

H gear ratio = 1.3, L gear ratio = 0.5

In this case, select OR SPEED 1 and select VS-626MTII gear at M GEAR.

(3) Stage 3rd gear

Table 40.3 OR SPEED Selection for Stage 3rd Gear

Gear ratio = $\frac{\text{Spindle speed}}{\text{Motor speed}}$	OR SPEED selection	VS-626MTII gear selection (Wiring)
H gear ratio 1.5 - 1.2	1	H GEAR (M GEAR OFF L GEAR OFF on page 35)
H gear ratio 1.1 - 0.9	2	
H gear ratio 0.8 - 0.6	3	
M gear ratio 0.6 - 0.15	Value selected at H gear ratio	M GEAR (M GEAR ON on page 35)
L gear ratio 0.2 - 0.05		L GEAR (L GEAR ON on page 35)

[EXAMPLE: Stage 3rd gear]

When H gear ratio = 1.2, M gear ratio = 0.4, and L gear ratio = 0.1.

Select OR SPEED by H gear ratio, and select VS-626MTII gear at M GEAR for M gear and L GEAR for L gear.



A Better Tomorrow for Industry through Automation

**YASKAWA Electric Mfg. Co., Ltd.**

**TOKYO OFFICE** Ohtemachi Bldg., Chiyoda-ku, Tokyo, 100 Japan  
Phone (03) 284-9111 Telex 222-2273 YASKWA J Fax (03) 284-9034

**SEOUL OFFICE** 4-5 Ka, Dongsan-Dong, Yeongdeungpo-Ku, Seoul, Korea  
Phone (635) 4324 Telex HHICO K 26471

**SINGAPORE OFFICE** CPF Bldg., 79 Robinson Road No. 24-03, Singapore 0106  
Phone 2217530 Telex (87) 24890 YASKAWA RS

**YASKAWA ELECTRIC EUROPE GmbH: SUBSIDIARY**  
Monchauerstrasse 1, 4000 Düsseldorf 11, West Germany  
Phone (0211) 501127 Telex (41) 8588673 YASD D Fax (0211) 507737

**YASKAWA ELECTRIC AMERICA, INC.: SUBSIDIARY**  
Los Angeles Office 14811 Myford Road, Tustin, California 92680, U.S.A.  
Phone (714) 731-5841 Telex (230) 678396 YASKAWAUS TSTN Fax (714) 730-8294

**Chicago Office (YASNAC America) 305 Eia Drive, Northbrook, Illinois 60062, U.S.A.**  
Phone (312) 564-0770 Telex (230) 270197 YSKW YSNC NBRK Fax (312) 564-3276

**YASKAWA CORPORATION OF AMERICA: SUBSIDIARY**  
14811 Myford Road, Tustin, California 92680, U.S.A.  
Phone (714) 731-7911 Telex (230) 678396 YASKAWAUS TSTN Fax (714) 730-8294

**YASKAWA ELETRICO DO BRASIL COMERCIO LTDA.: SUBSIDIARY**  
Av. Brig. Faria Lima, 1664-cj. 611, Pinheiros, São Paulo-SP, Brasil CEP-01452  
Phone (011) 212-5464, 813-3694 Telex (011) 24168 FERN BR

