YASKAWA

ACサーボパック Σ -Vシリーズ/大容量 Σ -Vシリーズ/

セーフティモジュール セーフティモジュール形式: SGDV-OSA01A


AC SERVOPACK

 Σ -V Series/

 Σ -V Series for Large-Capacity Models/ Σ -7 Series

Installation Guide

Safety Module Safety Module Model: SGDV-OSA01A



MANUAL NO. TORP C720829 06D


本資料はセーフティモジュールを Σ -V シリーズ/大容量 Σ -V シリーズ/ Σ -7 シ リーズサーボパックに取り付けるための手順書です。製品に同梱しております 「安全上のご注意」(資料番号: TOBP C720829 00) と併せて、お読みください。

一般注意事項

- ●本資料に掲載している図解は 細部を説明するために 装置のカバーまたは安全のための 遮へい物を取り外した状態で描かれている場合があります。この製品を運転するときは、必ず 規定どおりの装置のカバーや遮へい物を元どおりに戻し、ユーザーズマニュアルに従って
- •本資料に掲載されている図は代表事例であり、お届けした製品と異なる場合があります。
- •本資料は製品の改良や仕様変更,及び本資料自身の使いやすさの向上のために,適宜変更する ことがあります。この変更は,本資料の資料番号を更新し,改訂版として発行します。
- •損傷や紛失などにより本資料を注文される場合は、当社代理店または裏表紙に記載されている 最寄りの当社営業所へ, 資料番号を連絡してください。
- •お客様が改造を行った製品は、当社の品質保証の対象外となります。改造製品に起因する-切の障害や損傷に対して, 当社は責任を負いません。

安全に関するシンボルマーク

- 本資料では安全に関する内容により、以下のシンボルマークを使用しています。
- •安全に関するシンボルマークのある記述は、重要な内容を記載していますので必ず守ってくだ




取扱いを誤った場合に、危険な状況が起こりえて、中程度の傷害や軽傷を受け | 注意 | る可能性が想定される場合、及び物的損害のみの発生が想定される場合。


なお 🛆 注意 に記載した事項でも、状況によっては重大な結果に結びつく可能

対応サーボパック

 Σ -V シリーズ/大容量 Σ -V シリーズ/ Σ -7 シリーズ Σ -7S モデル

取付けに必要なもの





作業環境

以下の環境で取付け作業を行ってください。

- •取付け作業台に、導電マットまたは静電気防止マットを使用していること
- 導電マットまたは静電気防止マットが、1 $M\Omega\pm20\%$ を介して接地されていること
- ・周囲温度が0~55°Cであること
- •相対湿度が90%RH以下(凍結, 結露しないこと)であること
- 温度が急激に変化せず、結露しない場所
- 腐食性ガス, 可燃性ガスのない場所
- ちり、ほこり、塩分、金属粉が少ない場所
- •水,油,薬品などがかからない場所
- 振動や衝撃が直接本体に伝わらない場所

安全上のご注意

■作業前の注意

注意

•静電気防止リストストラップを接地し、必ず肌に密着させてください。 接地されているものに触れて、体の静電気を逃がしてください。

■取付け上の注意

注意

- •指定された作業環境で取付けを行ってください。 •基板の上に何も載せないでください。 故障のおそれがあります。 故障のおそれがあります。
- べて外した状態で取付けを行ってください。 故障のおそれがあります。
- 基板に衝撃を加えないでください。 故障のおそれがあります。
- 基板をぬらさないでください。 故障のおそれがあります。

故障のおそれがあります。

- 基板のコネクタ部や電子部品には触らないでく ださい。取付けの際は基板の端を持ってください。
- ・サーボパックに接続してあるケーブルをす •静電気対策処理が行われていない物に直接
 - 触れないでください。 故障のおそれがあります
 - •衣服を基板に接触させないでください。 故障のおそれがあります。
 - ねじを強く締めすぎないでください。推奨 締め付けトルクは0.49 N·m (+10%)です。 ねじ山がつぶれたり、スペーサがつぶれ基板 が変形するおそれがあります。

大容量 Σ -Vシリーズサーボパックをご使用の場合は、サーボパックから モジュールカバーを取り外して、手順3から始めてください。

サーボパックの準備

基板の取付け

差し込みます。

3. 図のように基板(A)の両側を

持ち, 基板コネクタ部をサーボ

パックコネクタ部にしっかりと

4. 基板をねじ (4個所) で固定

(締め付けトルク: 0.49 N·m)

します。

基板コネクタ部を

しっかり差し込む

基板にあらかじめ取付け

られている固定用ねじも

忘れずに締めてください。

1. 基板用取付板(F)をサーボ パック(I)の溝にあわせ, 取付板止めねじ(G)で固定 します。 (締め付けトルク: 0.49 N·m)

2. コネクタカバーを取り 外します。 コネクタカバー


F-基板用取付板

1-サーボパック


G-取付板止めねじ

モジュールカバーの準備

5. モジュールカバー(H) のフロントカバー (図の個所のみ)をマイナスドライバー (K)を使って外します。 ・他のフロントカバーは外さないでください。 フロントカバー (ここのみ取る) H-モジュールカバー 差し込んで外して K-マイナスドライバー



取付け完了



取付け完了後, 試運転を行ってください。 詳細については、ご使用のサーボパックのマニュアルを参照して ください。


(注) ご使用の前に、CN8に接続されているセーフティジャンパコネクタを 外してください。

修理・部品交換などで当社に製品を送る場合は

オプションモジュールをサーボパックに取付けたままの状態で当社に 送ってください。

モジュールカバーの取付け

7. モジュールカバー (H) の 開口部から基板が見える ように手前から取付け ます。



8. モジュールカバーの左右 のつめを内側に押し込み、 クめ突起部 サーボパックに固定します。 (矢印方向に押し込み, つめ突起部が完全に サーボパック内に入る ようにしてください。 つめ

ACサーボパック Σ -Vシリーズ/大容量 Σ -Vシリーズ/ Σ-7 シリーズ 取付手順書 セーフティモジュール

技術相談・アフターサービスに関するお問い合わせ(YASKAWAコンタクトセンタ)

TEL **0120-502-495** FAX 0120-394-094

●技術相談 ●資料請求

● アフターサービス相談

製品・技術情報サイト e-メカサイト





製造·販売 株式会社 安川雷機 www.vaskawa.co.ip

東京文社 TEJ (1981)84 148 74X (005)402-4581 〒105-6891 東京都西区海岸17目16語1号ニュービア竹芝サウスタワー6階 中部支店 TEJ (0561)86-8914 FAX (0561)86-9911 〒470-0217 資助開み上北市総東記で1百3番号 関西支店 TEJ (056408-8550 FAX (056)6480-8490 「〒600-0805 兵庫県尼崎市西長州町17日1番1号 九州支店 TEJ (092)288-7170 FAX (092)288-7179 〒7812-082 福間市時季6X票間71日14間60号

nics.com の「お問い合わせ」でご確認ください。

周辺機器・ケーブル

安川メカトレック末松九機株式会社 アカウント営業部 www.ym-c.co.jp TEL (03)5776-3136 FAX (03)5402-2566 〒105-6891 東京都港区海岸1丁目16番1号ニュービア竹芝5

関西事業所 TEI (06)6480-8442 技術的なお問い合わせ

ソトロール株式会社

YASKAWA 株式会社安川電機

YASKAWA

AC SERVOPACK


 Σ -V Series/

 Σ -V Series for Large-Capacity Models/ Σ -7 Series

Installation Guide

Safety Module

Safety Module Model: SGDV-OSA01A



MANUAL NO. TOBP C720829 06D

This installation guide explains how to mount the safety module onto the Σ -V, large-capacity Σ -V or Σ -7 Series SERVOPACK. Read this installation guide thoroughly as well as the safety precautions (Manual No.: TOBP C720829 00) included with the product.

General Precautions

- •The drawings presented in this instructions are sometimes shown without covers or protective guards. Always replace the equipment's cover or protective guard as specified first, and then operate the products in accordance with the user's manual.
- The drawings presented in this instructions are typical examples and may not match the product you received.
- •These instructions are subject to change due to product improvement, specification modification, and instructions improvement. When these instructions are revised, the instructions code is updated and the new instructions is published as a next edition.
- If the instructions must be ordered due to loss or damage, inform your nearest Yaskawa representative or one of the offices listed on the back of this instructions
- Yaskawa will not take responsibility for the results of unauthorized modifications of this product. Yaskawa shall not be liable for any damages or troubles resulting from unauthorized modification.

Safety Information

- •The following conventions are used to indicate precautions in these
- Failure to heed these precautions can result in serious or possibly even fatal injury or damage to the products or to related equipment and systems.



MARNING Indicates precautions that, if not heeded, could possibly result in loss of life or serious injury.


Indicates precautions that, if not heeded, could CAUTION result in relatively serious or minor injury, damage to the product, or faulty operation.


> In some situations, the precautions indicated could have serious consequences if not heeded

APPLICABLE SERVOPACKs

 Σ -V Series, Large-Capacity Σ -V Series or Σ -7 Series Σ -7S Models

TEMS REQUIRED FOR INSTALLATION





INSTALLATION CONDITIONS

Install the module in the following environment.

- •Cover the working area with a conductive or antistatic mat.
- •This mat must be safely grounded with a resistor (1 M $\Omega\pm20\%$).
- •The surrounding air temperature must be between 0 and 55°C.
- •Ambient humidity must be 90% RH or less (with no condensation).
- •No extreme changes in temperature that can cause condensation
- •Free from corrosive or flammable gases
- •Free from dust, salts, or iron dust
- •Not subject to water, oil, or chemicals
- •No vibration and/or shock directly transmitted to the product

SAFETY PRECAUTIONS

■ Before starting

CAUTION

- Always wear an antistatic wrist strap that is safely grounded.
- Touch a safely grounded object to discharge any static electricity
- Installation

CAUTION

- •Install in the specified environment.
- Failure to observe this caution may result in malfunction.
- Disconnect all cables from the SERVOPACK before installing the board. Failure to observe this caution may result in malfunction.
- Do not apply any impact to the board.
- Failure to observe this caution may result in malfunction.
- Protect the board from moisture. Failure to observe this caution may result in malfunction.
- •Do not touch the connector or electronic components on the board. Hold the board along its edges when installing.
- Failure to observe this caution may result in malfunction.
- Do not place any object on the board.
- Failure to observe this caution may result in malfunction.
- Avoid direct contact with any object that has not had antistatic treatment. Failure to observe this caution may result in malfunction
- Make sure that your clothing is not in contact with the board. Failure to observe this caution may result in malfunction
- Do not tighten the screws with excessive torque. The recommended tightening torque is 0.49 N·m $\pm 10\%$.
- Tightening screws with excessive torque may damage screw threads and the spacer, resulting in deformation of the board.


INSTALLATION PROCEDURE

For large-capacity Σ -V SERVOPACKs, remove the module cover from the SERVOPACK and start with step 3.


Preparing the SERVOPACK


1. Fit the mounting plate (F) into the recess on the SERVOPACK (I), and fix the plate with the mounting screws (G). (Tightening torque: 0.49 N⋅m) Back F-Mounting plate G-Mounting screws I-SERVOPACK

2. Remove the connector cover from the SERVOPACK.



Installing the Board





Preparing the Module Cover

5. Remove one of the front covers (shown in the illustration) from the module cover (H) with a screwdriver (K).

· Do not remove the other front covers.


Front cover (Remove only this cover.) H-Module cover Insert a screwdriver here K-Screwdriver to remove the front cover.

6. Affix three nameplates (C, D, E) to the positions specified in illustration. The product is under For details on where to affix warranty only when the the nameplate (E), refer to the nameplate (C) is attached. user's manual C-Nameplate (Ratings) D-Nameplate (Model no.)

E-Nameplate (Component code

Mounting the Module Cover

7. Align the front end of the module cover (H) with the front panel of the SERVOPACK as shown in the illustration, and place the module cover so that you can view the installed board from the opening (where the front cover is removed) on the module cover.



I-SERVOPACK

8. Fix the module cover Retention clip angled to the SERVOPACK end protrusion by pushing in the retention clips on the Push the clips in the left and right side of direction indicated by the arrow so the the module cover, clip will go into the SERVOPACK. while directing their angled end protrusions to enter the Retention clip SERVOPACK. Retention clip

After Installing

Conduct a trial operation after the safety module has been properly installed on the SERVOPACK.

For trial operation details, refer to the manual for SERVOPACK being

Note: Before using the SERVOPACK, remove the safety function jumper

If You Need to Send Us the Option Module for Service

Always leave the option module attached to the SERVOPACK when ending the option module to YASKAWA for service.

AC SERVOPACK Σ -V Series/ $\Sigma ext{-V}$ Series for Large-Capacity Models/ Σ -7 Series

Installation Guide Safety Module

ASKAWA ASIA PACIFIC PTE. LTD.

1A, Kallang Place, #08-01, 339213, Singaphone: +65-6282-3003 Fax: +65-6289-300

ASKAWA ELECTRIC (CHINA) CO., LTD. BEIJING OFFIC Room 1011, Tower W3 Oriental Plaza, No.1, East Chang An Avenue,

YASKAWA