*Note if you would like to use as a common you would have to jumper SN and AC.

Terminal	Description
Forward Run / Stop	S1
Reverse Run / Stop	S2
External fault	S3
Fault reset	S4
Multi-speed step 1	S5
Multi-speed step 2	S6
Jog speed	S7

ion
its
tting)

SN

SC

Sink / Source mode
selection wire link
(default: Sink) <4>

SP

+24 V <5>

FE

Please Add This Jumper when using the +P power supply

2 kΩ

<6> +V

A1 (Frequency Reference Bias)
0 to +10 Vdc (20 kΩ)
4 to 20 mA / 0 to 20 mA (250

A2 Analog Input 2
(Frequency Reference Bias)
0 to +10 Vdc (20 kΩ)
4 to 20 mA / 0 to 20 mA (250

AC

0 V

+P External power supply,
24 Vdc, max. 150 mA

Dri