Here is a comparison:

	Extended I/O Type	
	"I"	"J"
Pinout	- identical -	
Connectors	- identical -	
Mapping	- identical -	
Programming	- identical -	
Input type	- identical -	
Output type	relay contact	sinking

Go to page 2 of this document for flowchart.

The only item of concern is the output wiring. Follow the flowchart below to determine if the existing wiring is compatible with the "J" option board.

