

To run the motor faster than the rated RPMs Motor torque production is typically reduced by the square of the RPMs. Be sure that this is safe for the motor and machine.

n011	Frequency - Max.	50.0 to 400.0
------	------------------	---------------

When falling below the rated frequency, change the upper limit value for the frequency reference by n033.

n033	Frequency Reference Upper Limit	0. to 110
------	---------------------------------	-----------