









Speed / Torque Curves



**200V
Single-Phase**



**200V
Three-Phase**



**100V
Single-Phase**



* The peak torque available for these motors with LEGEND AC amps and 100VAC Systems are shown in dashed lines. The Continuous Duty rating curve is the same as shown, except with speed limitations (up to the crossover point with derated Peak Torque Rating (dashed lines)).

**A : CONTINUOUS
DUTY ZONE**

**B : INTERMITTENT
DUTY ZONE**