



Speed / Torque Curves

24V Servomotors



A : CONTINUOUS DUTY ZONE

B : INTERMITTENT DUTY ZONE