

Errata

Listed below are corrections and addition for the L1000A Technical Manual.
Please correct your manual accordingly.

◆ Applicable Documentation

Manual No.	Page	Chapter
SIEP C710616 32I	486	D.6
SIEP C710616 33H	438	D.4
SIEP C710616 38F	493	D.4

◆ Correction

Replace the tables in ■ *Standard Models (CIMR-L□□A□)* with the following tables.

■ Standard Models (CIMR-L□□A□)

Table Safety Standards and Applicable Harmonized Standards for CIMR-L□□A□

Safety Standards	Applicable Harmonized Standards
Functional Safety	IEC/EN 61508-1,2:2010 (SIL2)
Safety of Machinery	ISO/EN ISO 13849-1:2015 (Cat.3, PL d)
EMC	IEC 61800-3:2004/A1:2011 EN 61800-3:2004/A1:2012 EN 61000-6-2:2005/AC:2005
LVD	EN 61800-5-1:2007

◆ Addition

Add the following table to *Table Specifications for Safe Disable Function* in
◆ *Specifications*.

MTTF _D	High
DC _{avg}	CIMR-L□□A: Low CIMR-L□□F: Midium
Mission Time	10 years